

Recommendations for shoulder restraint installation in general aviation aircraft. AM 66-33

Young JW.
AM reports
1966; 1-16

ARTICLE IDENTIFIERS

DOI: unavailable
PMID: 5967302
PMCID: not available

JOURNAL IDENTIFIERS

LCCN: not available
pISSN: 1545-1518
eISSN: not available
OCLC ID: not available
CONS ID: not available
US National Library of Medicine ID: not available

This article was identified from a query of the SafetyLit database.