Problems during infusions. Severe electrical shock occurred during use of Welmed P1000 syringe pump

Ford P, Wood D.

British medical journal: BMJ

1995; 310(6989):1271

ARTICLE IDENTIFIERS

DOI: unavailable PMID: 7767221

PMCID: PMC2549655

JOURNAL IDENTIFIERS

LCCN: not available pISSN: 0959-8138 eISSN: 1468-5833 OCLC ID: not available CONS ID: not available

US National Library of Medicine ID: not available

This article was identified from a query of the SafetyLit database.