

Investigations of structural damage caused by the fertilizer plant explosion at West, Texas. II: ground shock

Dai K, Wang J, Huang Z, Felix Wu H.
Journal of performance of constructed facilities
2016; 30(4):e04015065

ARTICLE IDENTIFIERS

DOI: 10.1061/(ASCE)CF.1943-5509.0000800

PMID: unavailable

PMCID: not available

JOURNAL IDENTIFIERS

LCCN: not available

pISSN: 0887-3828

eISSN: 1943-5509

OCLC ID: not available

CONS ID: not available

US National Library of Medicine ID: not available

This article was identified from a query of the SafetyLit database.