

# **Assessment of the structural condition of a hospital-type building in Mexico City damaged in the 1985 earthquake**

Avila JA, Avila-Haro JA.

Key engineering materials

2017; 754:349-352

## **ARTICLE IDENTIFIERS**

DOI: [10.4028/www.scientific.net/KEM.754.349](https://doi.org/10.4028/www.scientific.net/KEM.754.349)

PMID: unavailable

PMCID: not available

## **JOURNAL IDENTIFIERS**

LCCN: 86655889

pISSN: 1013-9826

eISSN: 1662-9795

OCLC ID: 14050315

CONS ID: not available

US National Library of Medicine ID: 101296901

This article was identified from a query of the SafetyLit database.