

Sudden collapse of a 19th-century masonry structure during its renovation process

Krentowski J, Chyzy T, Dunaj P.

Engineering failure analysis

2017; 82:540-553

ARTICLE IDENTIFIERS

DOI: 10.1016/j.engfailanal.2017.04.010

PMID: unavailable

PMCID: not available

JOURNAL IDENTIFIERS

LCCN: not available

pISSN: 1350-6307

eISSN: not available

OCLC ID: not available

CONS ID: not available

US National Library of Medicine ID: not available

This article was identified from a query of the SafetyLit database.