## Sudden collapse of a 19th-century masonry structure during its renovation process

Krentowski J, Chyzy T, Dunaj P. Engineering failure analysis 2017; 82:540-553

## **ARTICLE IDENTIFIERS**

DOI: 10.1016/j.engfailanal.2017.04.010

PMID: unavailable PMCID: not available

## **JOURNAL IDENTIFIERS**

LCCN: not available pISSN: 1350-6307 eISSN: not available OCLC ID: not available CONS ID: not available

US National Library of Medicine ID: not available

This article was identified from a query of the SafetyLit database.