

## **'Design flaw' blamed for EO gas leakage: thousands of hospitals may be affected**

Ruck D.

American medical news

1978; 21(28):11

### **ARTICLE IDENTIFIERS**

DOI: unavailable

PMID: 10308641

PMCID: not available

### **JOURNAL IDENTIFIERS**

LCCN: not available

pISSN: 0001-1843

eISSN: not available

OCLC ID: not available

CONS ID: not available

US National Library of Medicine ID: not available

This article was identified from a query of the SafetyLit database.