

An investigative report concerning safety and management in the magnetic resonance environment: There are more accidents than expected

Doi T, Yamatani Y, Ueyama T, Nishiki S, Ogura A, Kawamitsu H, Tsuchihashi T, Okuaki T, Matsuda T, Kumashiro M.

Nihon Hoshasen Gijutsu Gakkai Zasshi

2011; 67(8):895-904

ARTICLE IDENTIFIERS

DOI: unavailable

PMID: 21869543

PMCID: not available

JOURNAL IDENTIFIERS

LCCN: not available

pISSN: 0369-4305

eISSN: 1881-4883

OCLC ID: 50377136

CONS ID: not available

US National Library of Medicine ID: 7505722

This article was identified from a query of the SafetyLit database.