

## **Measurement of roof deformation caused by vehicle rollover**

Yoon HS, Lee KT, Ahn SH.

International journal of automotive technology

2013; 14(4):667-674

### **ARTICLE IDENTIFIERS**

DOI: 10.1007/s12239-013-0072-5

PMID: unavailable

PMCID: not available

### **JOURNAL IDENTIFIERS**

LCCN: not available

pISSN: 1229-9138

eISSN: 1976-3832

OCLC ID: not available

CONS ID: not available

US National Library of Medicine ID: not available

This article was identified from a query of the SafetyLit database.