

Determination of fire fused traces caused by automotive electrical wiring harness using metallographic method

Huang G, Sun S, Bu H, Ji F.

Procedia engineering

2012; 43:348-352

ARTICLE IDENTIFIERS

DOI: 10.1016/j.proeng.2012.08.060

PMID: unavailable

PMCID: not available

JOURNAL IDENTIFIERS

LCCN: not available

pISSN: 1877-7058

eISSN: not available

OCLC ID: 464210789

CONS ID: not available

US National Library of Medicine ID: not available

This article was identified from a query of the SafetyLit database.