

Investigation on the geological and geotechnical factors leading to a major slope failure at a selected site on a Jordanian highway

Al-homoud AS, Taqieddin S, Saket S.

Natural hazards

1995; 12(3):203-224

ARTICLE IDENTIFIERS

DOI: 10.1007/BF00596221

PMID: unavailable

PMCID: not available

JOURNAL IDENTIFIERS

LCCN: not available

pISSN: 0921-030X

eISSN: 1573-0840

OCLC ID: not available

CONS ID: not available

US National Library of Medicine ID: not available

This article was identified from a query of the SafetyLit database.