An investigation on the mechanisms of instabilities and safe design of the south slope at a lignite pit (SW Turkey) based on a sensitivity approach

Solak KC, Tuncay E, Ulusay R. Bulletin of engineering geology and the environment 2017; 76(4):1321-1341

ARTICLE IDENTIFIERS

DOI: 10.1007/s10064-017-1025-4

PMID: unavailable PMCID: not available

JOURNAL IDENTIFIERS

LCCN: not available pISSN: 1435-9529 eISSN: 1435-9537 OCLC ID: 635690809 CONS ID: not available

US National Library of Medicine ID: not available

This article was identified from a query of the SafetyLit database.