

Lateral buckling failure of steel cantilever roof of a tribune due to snow loads

Altuni?ik AC, Ate?, Hüsem M.
Engineering failure analysis
2017; 72:67-78

ARTICLE IDENTIFIERS

DOI: 10.1016/j.engfailanal.2016.12.010
PMID: unavailable
PMCID: not available

JOURNAL IDENTIFIERS

LCCN: not available
pISSN: 1350-6307
eISSN: not available
OCLC ID: not available
CONS ID: not available
US National Library of Medicine ID: not available

This article was identified from a query of the SafetyLit database.