

Condition survey and evaluation of an early post-tensioned bridge verified after removal

Vogel T, Fricker S.

Structure and infrastructure engineering: maintenance, management, life-cycle design and performance

2014; 10(3):359-374

ARTICLE IDENTIFIERS

DOI: 10.1080/15732479.2012.756917

PMID: unavailable

PMCID: not available

JOURNAL IDENTIFIERS

LCCN: not available

pISSN: 1573-2479

eISSN: 1744-8980

OCLC ID: not available

CONS ID: not available

US National Library of Medicine ID: not available

This article was identified from a query of the SafetyLit database.