Hazard report. Overlap of surgical lighthead beams may present burn risk

Health devices 2009; 38(10):341-342

ARTICLE IDENTIFIERS

DOI: unavailable PMID: 20853770 PMCID: not available

JOURNAL IDENTIFIERS

LCCN: not available pISSN: 0046-7022 eISSN: not available OCLC ID: 02242189 CONS ID: not available

US National Library of Medicine ID: 1262063

This article was identified from a query of the SafetyLit database.