

Delayed fracture of glass bulbs used in fire sprinklers

Huet R, Martorano S, Ames N, Currens E.

Fire technology

2017; 53(2):629-647

ARTICLE IDENTIFIERS

DOI: 10.1007/s10694-016-0584-4

PMID: unavailable

PMCID: not available

JOURNAL IDENTIFIERS

LCCN: 65009890

pISSN: 0015-2684

eISSN: 1572-8099

OCLC ID: 1569307

CONS ID: FITCAA

US National Library of Medicine ID: not available

This article was identified from a query of the SafetyLit database.