

Analysis of high speed instability of weave mode in motorcycle by using energy flow method

Tamoto H, Kimura T, Miki M, Katayama T.

Transactions of Society of Automotive Engineers of Japan

2019; 50(5):1355-1359

ARTICLE IDENTIFIERS

DOI: 10.11351/jsaeronbun.50.1355

PMID: unavailable

PMCID: not available

JOURNAL IDENTIFIERS

LCCN: not available

pISSN: 0287-8321

eISSN: 1883-0811

OCLC ID: 1076728522

CONS ID: not available

US National Library of Medicine ID: not available

This article was identified from a query of the SafetyLit database.